

From: [Miller, Garyg](#)
To: [David Keith](#)
Cc: [Dave Moreira \(dmoreira@wm.com\)](#); [Phil Slowiak](#); [Wendell Mears](#); [Rick Coupe](#); [John Laplante](#); [John Verduin](#); [Tzhone, Stephen](#); [Sanchez, Carlos](#); [Walters, Donn](#); [Satya Dwivedula](#); [Bob Allen](#); [Linda Henry](#); [Garry McMahan](#); [Leah Oberlin \(loberlin@poha.com\)](#); [angela.sunley@glo.texas.gov](#); [Walker, Tina \(DSHS\)](#)
Subject: RE: San Jacinto Western Area Inspection Update
Date: Wednesday, June 15, 2016 4:17:00 PM

David,

The EPA approves the plan presented below with one modification:

- AOI-22 (2' x 4') shall be repaired with C-rock.

Please proceed with this work as described below.

Regards,

Gary Miller
Remedial Project Manager
EPA Region 6 Superfund Division, TX/Ark Section
214-665-8318
miller.garyg@epa.gov

From: David Keith [<mailto:dkeith@anchorqea.com>]
Sent: Wednesday, June 15, 2016 9:12 AM
To: Miller, Garyg <Miller.Garyg@epa.gov>
Cc: Dave Moreira (dmoreira@wm.com) <dmoreira@wm.com>; Phil Slowiak <philip.slowiak@ipaper.com>; Wendell Mears <wmears@anchorqea.com>; Rick Coupe <rcoupe@anchorqea.com>; John Laplante <jlaplante@anchorqea.com>; John Verduin <jverduin@anchorqea.com>; Tzhone, Stephen <tzhone.stephen@epa.gov>
Subject: San Jacinto Western Area Inspection Update

Gary - We completed the AOI probing yesterday with Steve Tzhone and Nick. There are a few areas that will require maintenance. Wendell is meeting with the Steve and Nick this morning to confirm the findings, and then the GIS teams will coordinate to ensure that the data sets match. Benchmark is available to complete the required maintenance later in the week, and USA will bring enough stone today to complete the upland maintenance as well as the areas identified yesterday.

Preliminary findings are below:

- 6 small (1'X1') locations that require repair: AOIs 12, 13, 22, 9, 9b, and 7. Most of these areas had some sand/sediment but had less gravelly aggregate than the surrounding areas.
- 1 10' X 3' location encompassing AOIs 15a, 15b, and 16. This area was denoted as "depression area" in the memo and table. The cap is intact around the edges and had a lot of sand with not as much gravel in the bottom.



9807339

We will follow the maintenance plan provided in the approved work plan, submitted to you on June 10, 2016 to address the areas above. We are planning on providing a geotextile base similar to what we did for the December maintenance event in the 10' x 3' location. Please provide your approval for that approach.

We will begin NW Area probing with Benchmark tomorrow morning. USA is mobilizing to the site today to begin maintenance on the upland side. Please let me know if you have any questions.

Thank you,
David

David Keith
Anchor QEA, LLC

Phone: 228-220-1156
Cell: 228-224-2983
[*dkeith@anchoragea.com*](mailto:dkeith@anchoragea.com)

ANCHOR QEA, LLC
www.anchoragea.com

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at (228) 818-9626.